

AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple listee model(s) identified on the correlation page of the Listing Report.

This document is the property of Intertek Testing Services and is not transferable. The certification mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

Applicant: Dana Innovations dba Trufig

212 Avenida Fabricante

San Clemente CA 92672

Country: USA

Address:

Contact: Mr. Alex Bertagni/Hamaad Akmal

Phone: (949) 492-7777 **FAX:** NA

Email: alexb@sonance.com

Party Authorized To Apply Mark: Report Issuing Office:

Apply Mark: Same as Manufacturer Lake Forest, CA

Control Number: 3174272 Authorized by:

Manufacturer: Dana Innovations dba Trufig

Address: 212 Avenida Fabricante San Clemente CA 92672

Country: USA

Contact: Mr. Alex Bertagni/Hamaad Akmal

Phone: (949) 492-7777

FAX: NA

Email:

alexb@sonance.com

Ellenfuialek

for Thomas J. Patterson, Certification Manager



Intertek

This document supersedes all previous Authorizations to Mark for the noted Report Number.

This Authorization to Mark is for the exclusive use of Intertek's Client and is provided pursuant to the Certification agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Authorization to Mark. Only the Client is authorized to permit copying or distribution of this Authorization to Mark and then only in its entirety. Use of Intertek's Certification mark is restricted to the conditions laid out in the agreement and in this Authorization to Mark. Any further use of the Intertek name for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect.

Intertek Testing Services NA Inc. 545 East Algonquin Road, Arlington Heights, IL 60005 Telephone 800-345-3851 or 847-439-5667 Fax 312-283-1672

Standard(s):

Standard for Safety for Metallic Outlet Boxes, UL 514A Dated: 02/16/2004, Ed:10, Rev: April, 15, 2010. Metallic Outlet Boxes - General Instruction No.1: 2006/02/01, General Instruction No.2: 2007/08/01, (R2009), General Instruction No. 3: 2009/10/27, General Instruction No.4: 2010/04/15, CSA C22.2#18.1,

Issued:2004/02/16 Ed:1

Product: Metal Boxes

Models: Single gang models 50256, 50206, 50208, 50217 and double gang models 50217, 50257, 50209, 50216

ATM Issued: 19-Aug-2015



AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple listee model(s) identified on the correlation page of the Listing Report.

This document is the property of Intertek Testing Services and is not transferable. The certification mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

Applicant: Dana Innovations dba Trufig

212 Avenida Fabricante

Address: San Clemente CA 92672

Country: USA

Contact: Mr. Alex Bertagni/Hamaad Akmal

Phone: (949) 492-7777

FAX: NA

Email: alexb@sonance.com

Party Authorized To Apply Mark:

Report Issuing Office:

Same as Manufacturer

Lake Forest, CA

Control Number: 4010821

Authorized by:

Manufacturer: Right Hand Manufacturing

Address: Boulevard de Insurgentes #19802-7

Cerro Colorado, Tijuana

Country: Mexico

Contact: Mr. Jorge Velazco/Luis Resendiz

Phone: (664) 903-0882

FAX: NA Email: NA

Ellen fuialek

for Thomas J. Patterson, Certification Manager



Intertek

This document supersedes all previous Authorizations to Mark for the noted Report Number.

This Authorization to Mark is for the exclusive use of Intertek's Client and is provided pursuant to the Certification agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Authorization to Mark. Only the Client is authorized to permit copying or distribution of this Authorization to Mark and then only in its entirety. Use of Intertek's Certification mark is restricted to the conditions laid out in the agreement and in this Authorization to Mark. Any further use of the Intertek name for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect.

Intertek Testing Services NA Inc. 545 East Algonquin Road, Arlington Heights, IL 60005 Telephone 800-345-3851 or 847-439-5667 Fax 312-283-1672

Standard(s):

Standard for Safety for Metallic Outlet Boxes, UL 514A Dated: 02/16/2004, Ed:10, Rev: April, 15, 2010. Metallic Outlet Boxes - General Instruction No.1: 2006/02/01, General Instruction No.2: 2007/08/01, (R2009), General Instruction No. 3: 2009/10/27, General Instruction No.4: 2010/04/15, CSA C22.2#18.1,

Issued:2004/02/16 Ed:1

Product: Metal Boxes

Models: Single gang models 50256, 50206, 50208, 50217 and double gang models 50217, 50257, 50209, 50216

ATM Issued: 19-Aug-2015

ATM for Report 100067729LAX-001a

Page 2 of 2

ED 16.3.15 (1-Jan-13) Mandatory